

Caring for your Scale

Clean the scale with a slightly damp cloth.
Do not use a corrosive cleaner.

The scale is not waterproof. Do not immerse directly into water.

Store your scale in a clean, dry location. Dust, dirt and moisture can accumulate on the weighing sensors and cause the scale to malfunction.

Do not attempt to dismantle the scale.

It does not contain parts that may be repaired by the user.

Do not subject the scale to extreme temperatures.

Remove the batteries if the scale is not being used for a long period of time.

Battery Warning

BATTERY WARNING:

INTERNAL BURNS / CHOKING HAZARD

Swallowing batteries may lead to serious injury or death (severe burns can occur within 2 hours).

IMMEDIATELY SEE A DOCTOR

Emergency Telephone Numbers

AUSTRALIA 000 NEW ZEALAND 111

Poisons Information Centre

AUSTRALIA 13 1126 NEW ZEALAND 0800 764 766

KEEP BATTERIES OUT OF REACH OF CHILDREN

Dispose of batteries immediately and responsibly

- Non-rechargeable batteries are not to be recharged.
- Only batteries of the same or equivalent type are to be used.
- Batteries are to be inserted with the correct polarity.
- Remove exhausted batteries from the product.
- Remove batteries from the battery compartment when not in use.
- Never throw batteries in a fire or attempt to open up their outer casing.

Specifications

Model 1340

Capacity: 5000g / 176.35 fl.oz /
11lb:0.4oz / 5000ml.

Graduation: 1g / 0.05 fl.oz / 0.1oz / 1ml

Tare weigh function

Measures water volume in ml or fl.oz

Brushed stainless steel

Touch sensors

Auto Off

LCD readout

Battery: 4 x AAA Alkaline Batteries

Made in China for
Proper Housewares
A division of
SUPERTEX INDUSTRIES PTY LTD
- a wholly-owned Australian company
ABN 85 003 833 029

For further information -

website: www.supertex.com.au

Email: customerservice@supertex.com.au

Telephone: (02) 8756 3000

Facsimile: (02) 9748 6622



A signatory to the
Australian Packaging Covenant

N2853



V1.1212

proper[®]
5kg slimline
stainless steel
digital scale

In your home since 1920

Model 1340

Name: Digital Steel Scale




Operating Instructions

Instructions for use

Remove all packaging before first using the scale.

1. Purchase four AAA Alkaline batteries. After removing the battery compartment cover on the bottom of the scale, insert the batteries, making sure the positive (+) and negative (-) terminals are correctly positioned. Replace the battery compartment cover and turn the scale the correct way up.



FUNCTION KEYS

UNIT
SELECTION
BUTTON

UNIT

ON / OFF /
TARE BUTTON

ON/OFF/TARE




1. Place the scale on a hard, level surface. If you intend using a bowl or container, place it on the platform first before switching it on.

2. To turn the scale on, press **ON/OFF/TARE**.

3. The full display appears for about 2 seconds before it 'zeros' indicating it is now ready for use.

4. Should you wish to change the unit measure, press **UNIT**. The screen displays in the following sequence - lb/oz....g....ml...fl oz....

5. Place the object or ingredients directly onto the platform, or in the bowl or container placed securely on the platform. Ensure the scale readout shows zero before weighing, otherwise, press **ON/OFF/TARE** to reset it.




To use the tare weighing function

This scale allows the separate weighing of items as they are added onto the scale. No need to empty the bowl or container!

1. After weighing the first item on the scale and with this first item still on the scale, press **ON/OFF/TARE** to reset the display to zero.
2. Add the second item to the scale. The scale will now display the weight of the second item only.
3. If you have additional items to weigh, repeat Steps 1. and 2. The total weight of all the items on the scale, (including the bowl or container if using one), must not exceed the capacity of the scale, which is 5000g / 176.35fl.oz / 11lb:0.4oz / 5000ml.
4. The total weight of the items on the scale, (including the container or bowl if using one), can be obtained by first pressing **ON/OFF/TARE**, then removing all items from the scale. The total weight will be displayed as a minus figure.

To turn the scale off

Turn the scale off at any time by holding down **ON/OFF/TARE** for approximately 2 seconds. If left idle, the scale will switch off automatically after approximately 60 seconds.



Display value

To measure water

1. Place the container or jug on the scale before switching it on.
2. After you have turned the scale on, press **UNIT** and select either the 'ml' or 'fl.oz' unit
3. The scale is ready for use when it is 'zeroed'
4. Begin pouring water into the container, checking the display at the same time. Stop when the volume reaches your need.
5. Tare feature functions as normal

Overloading

If the scale is overloaded, 'Err' will be displayed. Remove the weight immediately or damage to the scale may occur.

Low battery indicator



The low battery symbol will appear on the readout indicating the batteries need to be changed. Replace the batteries with fresh, good quality Alkaline ones, making sure the positive (+) and negative (-) terminals are correctly positioned.